



M221 Series

Type: 2/2 Port Size: 1/8" Working Pressure: 0-8Bar Working Temperature: -5~80°C



MJ322 Series

Type: 3/2 Port Size: 1/4" Working Pressure: 0-8Bar Working Temperature: -5~80°C



M322 Series

Type: 3/2 Port Size: 1/4" Working Pressure: 0-8Bar Working Temperature: -5~80°C



M522 Series

Type: 5/2 Port Size: 1/4" Working Pressure: 0-8Bar Working Temperature: -5~80°C



Hand Pull Valve


Working Pressure: 0–8Bar Working Temperature: –5° 80°C


Flow Control Valve


Working Pressure: 0–8Bar Working Temperature: –5° 80°C


Hand Push Valve

Working Pressure: 0–8Bar Working Temperature: –5° 80°C


Foot Valve

Port Size: 1/4" Working Pressure: 0–8Bar Working Temperature: –5° 80°C


Rotary Valve

Type: 4/3 Working Pressure: 0–8Bar Working Temperature: –5° 80°C


Shuttle Valve
Quick Exhaust Valve
One Way Valve
Slide Valve
Pressure increase Valve

Working Pressure: 1.5–10Bar Working Temperature: –5° 60°C

